	Туре	Hits	Search Text	DBs
1	BRS	198	3,631,324 3,786,312 4,016,518 4,027,204 4,318,156 4,333,119 4,415,943 5,097,383 5,111,127 5,233,497 5,243,488 5,245,499 5,532,894 5,544,003	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
2	BRS	163553 6	5,587,862 5,668,692 5,757,597 5,774,319 5,894,392 6,301,338 B1 6,516,966 B1 6,545,347 B1	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
3	BRS	59	5,587,862 5,668,692 5,757,597 5,774,319 5,894,392 6,301,338 6,516,966 6,545,347	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
4	BRS	20	3,631,324	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
5	BRS	39	portable adj distribution	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
6	BRS	12	over adj voltage same under adj voltage near relay	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
7	BRS	21	over adj voltage and under adj voltage near relay	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
8	BRS	10	(over adj voltage and under adj voltage) near relay	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
9	BRS	8	("3059164" "3192464" "3234450" "3383582" "3657631" "3702434" "3743920" "3843919").PN.	USPAT
10	BRS	8	4070701.URPN.	USPAT
11	BRS	3	("4335413" "6107784" "6456056").PN.	USPAT

	Time Stamp	Comments	Error Definition	Errors
1	2004/10/04 09:12	•		0
2 .	2004/10/01 15:12	·		0
3	2004/10/01 15:13			0
4	2004/10/01 15:42			0
5	2004/10/01 15:47			0
6	2004/10/01 16:17			0
7	2004/10/01 15:55			0
8	2004/10/01 15:55			0
9	2004/10/01 16:11			0
10	2004/10/01 16:12 2004/10/01 16:14			0
	7004/10/01 TO:14			U

	Туре	Hits	Search Text	DBs
1.0	DDG		261/01/ 1	USPAT; US-PGPUB;
12	BRS	0	361/91/.1	EPO; JPO; DERWENT; IBM_TDB
13	BRS	0	361/91/1	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB
14	BRS	782	361/91.1	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
15	BRS	3918	momentary adj (switch push adj button)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
16	BRS	1119	momentary adj (switch push adj button) and (latch latching)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
17	BRS	351	momentary adj (switch push adj button) same (latch latching)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
18	BRS	23	momentary adj (switch push adj button) same (latch latching) and circuit adj breaker	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
19	BRS	4	momentary adj (switch push adj button) same (latch latching) adj relay and circuit adj breaker	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
20	BRS	83	(over adj voltage and under adj voltage) same relay	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
21	BRS	28	(over adj voltage and under adj voltage) same (contact contactor)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
22	BRS	0	(over adj voltage and under adj voltage) near (contact contactor)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
23	BRS	8	5,894,392	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
24	BRS	13	4,070,701	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
25	BRS	4	("3783354" "4532569" "5418678" "5786971").PN.	USPAT
26	BRS	4	("3783354" "4532569" "5418678" "5786971").PN.	USPAT
27	BRS	5	5894392.URPN.	USPAT
28	BRS	13	3,548,259	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
29	BRS	10	4,197,567	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
30	BRS	6	4197567.URPN.	USPAT ·

	Time Stamp	Comments	Error Definition	Errors
12	2004/10/01 16:17			0
13	2004/10/01 16:17			0
14	2004/10/01 16:18			0
15	2004/10/03 11:03			0
16	2004/10/03 11:04			0
17	2004/10/03 11:04			0
18	2004/10/03 11:16			0
19	2004/10/03 11:16			0
20	2004/10/03 13:01			0
21	2004/10/03 12:03			0
22	2004/10/03 11:43			0
23	2004/10/03 14:57			0
24	2004/10/03 13:34			0
25	2004/10/03 14:51			0
26	2004/10/03 14:55			0
27	2004/10/03 14:55			0
28	2004/10/03 15:00			0
29	2004/10/03 16:27			0
30	2004/10/03 15:02			0

10/06/2004, EAST Version: 1.4.1

	Туре	Hits	Search Text	DBs
31	BRS	1098	361/45	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
32	BRS	8	5,894,392	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
33	BRS	19	over adj voltage and threshold adj adjustment	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
34	BRS	13	under adj voltage and threshold adj (adjust adjusted adjusting adjustable)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
35	BRS	55	(under over) adj voltage and threshold adj (adjust adjusted adjusting adjustable)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
36	BRS	0	(under over) adj voltage same threshold adj (adjust adjusted adjusting adjustable)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
37	BRS	0	relay near turn adj on and threshold adj (adjust adjusted adjusting adjustable)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
38	BRS	1	relay near threshold adj (adjust adjusted adjusting adjustable)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB
39	BRS	30	relay same threshold adj (adjust adjusted adjusting adjustable)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
40	BRS	0	relay near turn adj on and hysteresis	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
41	BRS	47	relay adj hysteresis	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
42	BRS	13	relay adj hysteresis same switch	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
43	BRS	18	relay adj switching adj voltage	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
44	BRS	23	relay near switching adj voltage	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
45	BRS	0	relay near switching adj voltage same release adj voltage	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
46	BRS	0	relay same switching adj voltage same release adj voltage	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
47	BRS	464	relay same hysteresis same switch	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB

	Time Stamp	Comments	Error Definition	Errors
31	2004/10/03 16:28			0
32	2004/10/04 10:28			0
33	2004/10/04 10:45			0
34	2004/10/04 10:49			0
35	2004/10/04 10:54			0
36	2004/10/04 10:50			0
37	2004/10/04 10:55			0
38	2004/10/04 10:55			0
39	2004/10/04 11:29			0
40	2004/10/04 11:31			0
41	2004/10/04 11:31			0
42	2004/10/04 12:17			0
43	2004/10/04 12:16			0
44	2004/10/04 12:16			0
45	2004/10/04 12:16			0
46	2004/10/04 12:16			0
47	2004/10/04 12:17			0

	Туре	Hits	Search Text	DBs
48	BRS	1	relay near hysteresis and (switch switching) adj voltage	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB
49	BRS	2	relay same hysteresis and (switch switching) adj voltage and release	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
50	BRS	43	relay same hysteresis and (switch switching) adj voltage	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
51	BRS	2	relay and (switch switching) adj voltage and release adj voltage	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
52	BRS	1	"5164636".PN.	USPAT
53	BRS	13	GFCI and "30" adj (amper A)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
54	BRS	4	plug and "250" adj vac and "50" adj (amp A)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
55	BRS	11	5,841,617	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
56	BRS	151	GFCI and fuse	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
57	BRS	2	GFCI near fuse	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
58	BRS	53	GFCI same fuse	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
59	BRS	6	GFCI same fuse and miswiring	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
60	BRS	4	GFCI same fuse and over adj voltage	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
61	BRS	10	5,418,678	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
62	BRS	0	relay and activation adj voltage same retain adj voltage	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
63	BRS	0	relay and pick adj voltage same retain adj voltage	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
64	BRS	499	relay and pull adj2 voltage	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
65	BRS	93	relay and pull adj2 voltage and drop adj2 voltage	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB

	Time Stamp	Comments	Error Definition	Errors
48	2004/10/04 12:17			0
49	2004/10/04 12:18			0
50	2004/10/04 12:23			0
51	2004/10/04 12:25			0
52	2004/10/04 12:25			0
53	2004/10/04 14:43			0
54	2004/10/04 15:01			0
55	2004/10/04 15:17			0
56	2004/10/04 15:17			0
57	2004/10/04 15:17			0
58	2004/10/04 15:33			0
59	2004/10/04 15:20			0
60	2004/10/04 15:21			0
61	2004/10/04 15:54			0
62	2004/10/04 15:55			0
63	2004/10/04 15:55			0
64	2004/10/04 15:56			0
65	2004/10/04 15:56			0

	Туре	Hits	Search Text	DBs
66	BRS	31	relay same pull adj2 voltage and drop adj2 voltage	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
67	BRS	777	361/78	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
68	BRS	2212	361/42	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
69	BRS	313	361/46	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB

	Time Stamp	Comments	Error Definition	Errors
66	2004/10/04 15:56			0
67	2004/10/04 16:57			0
68	2004/10/05 11:25			0
69	2004/10/05 16:36			0